C.L. "BUTCH" OTTER - Governor RICHARD M. ARMSTRONG - Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-maii: fsb@dhw.idaho.gov

January 28, 2010

Tom Whittemore, Administrator Communicare #3 (Pond) 40 West Franklin Road Suite F Meridian, Idaho 83642

RE: Communicare #3 (Pond), Provider # 13G010

Dear Mr. Whittemore:

This is to advise you of the findings of the Medicaid/Licensure Fire Life Safety Survey, which was concluded at Communicare #3 (Pond), on January 21, 2010.

Enclosed is a Statement of Deficiencies/Plan of Correction, Form CMS-2567, listing Medicaid deficiencies and a similar form listing State licensure deficiencies. In the spaces provided on the right side of each sheet, please provide a Plan of Correction. <u>It is important</u> that your Plan of Correction address each deficiency in the following manner:

- 1. What corrective action(s) will be accomplished for those individuals found to have been affected by the deficient practice;
- 2. How you will identify other individuals having the potential to be affected by the same deficient practice and what corrective action(s) will be taken;
- 3. What measures will be put in place or what systemic change you will make to ensure that the deficient practice does not recur;
- 4. How the corrective action(s) will be monitored to ensure the deficient practice will not recur, i.e., what quality assurance program will be put into place; and,

Tom Whittemore, Administrator January 28, 2010 Page 2 of 2

5. Include dates when corrective action will be completed. 42 CFR 488.28 states ordinarily a provider is expected to take the steps needed to achieve compliance within 60 days of being notified of the deficiencies. Please keep this in mind when preparing your plan of correction. For corrective actions which require construction, competitive bidding, or other issues beyond the control of the facility, additional time may be granted.

Sign and date the form(s) in the space provided at the bottom of the first page.

After you have completed your Plan of Correction, return the original to this office by **February 10, 2010**, and keep a copy for your records.

Thank you for the courtesies extended to us during our visit. If you have any questions, please call or write this office at (208) 334-6626.

Sincerely,

Wildly Kanson for ERIC MUNDELL, REHS

Health Facility Surveyor

Facility Fire Safety and Construction Program

EM/lj

Enclosures

Printed: 01/25/2010 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION

A. BUILDING

(X3) DATE SURVEY COMPLETED

13G010

B. WING

01/21/2010

NAME OF PROVIDER OR SUPPLIER

COMMUNICARE INC., #3 (POND)

STREET ADDRESS, CITY, STATE, ZIP CODE

2650 S. POND STREET **BOISE, ID 83705**

	BOISE	, ID 83/US		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 000	INITIAL COMMENTS	K 000		
	The facility is a single story Type V (000) residential building. It is sprinklered in living spaces and closets. It has a complete fire alarm/smoke detection system. Currently the building is licensed for 8 ICF-MR beds. The survey was conducted in accordance with the Life Safety Code, 2000 edition, Chapter 33, Existing Residential Board and Care Occupancy, Impractical Evacuation Capability and 42 CFR 483.470		RECEIVED FEB 1 6 2010 FACILITY STANDARDS	
	The following deficiency was cited during the fire/life safety survey on January 21, 2010 The annual fire/life safety survey was conducted by: Eric Mundell REHS Health Facility Surveyor Facility Fire/Life Safety and Construction Program			
K0056	483.470(j)(1)(i) LIFE SAFETY CODE STANDARD PROMPT Where an automatic sprinkler system is installed, for either total or partial building coverage, the system is in accordance with Section 9.7,	K0056	K0156 We have spoken with Viking Automatic Sprinkler who completes our annual a system inspections and	3/31/20
	33.2.3.5.2 and activates the fire alarm system in accordance with 33.2.3.4.1. The adequacy of the water supply is documented to the authority having jurisdiction. Exception No. 1: In prompt evacuation facilities, an automatic sprinkler system in accordance with NFPA 13D, Standard for the Installation of	:	repairs regarding the need for replacement sprinkler heads. They will visit the home and determine the types of sprinkler heads needed and obtain the necessary heads. The system is at present fully	

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

Printed: 01/25/2010 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION

A. BUILDING 02

(X3) DATE SURVEY COMPLETED

13G010

B. WING

01/21/2010

NAME OF PROVIDER OR SUPPLIER

COMMUNICARE INC., #3 (POND)

STREET ADDRESS, CITY, STATE, ZIP CODE

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K0056	Sprinkler Systems in One and two Family Dwellings and Manufactured Homes, is permitted. Automatic sprinklers are not required in closets not exceeding 24 sq. ft. and in bathrooms not exceeding 55 sq. ft., provided that such spaces are finished with lath and plaster or materials providing a 15 minute thermal barrier.	K0056	operational, however depending on availability it may take longer than our target date of March 31, 2010. Every effort will be made to obtain the needed heads in a timely manner.	
	Exception No. 2: Not applicable Exception No. 3: In prompt and slow evacuation capability facilities where an automatic sprinkler system is in accordance with NFPA 13, Standard for the Installation of Sprinkler Systems, automatic sprinklers are not required in closets not exceeding 24 sq. ft and in bathrooms not exceeding 55 sq. ft., provided that such spaces are finished with lath and plaster or material providing a 15 minute thermal barrier. Exception No. 4: In prompt and slow evacuation capability facilities up to and including four stories in height, systems in accordance with NFPA 13R, Standard for the Installation of Sprinkler Systems in Residential Occupancies up to and Including Four Stories in Height, are permitted.		The AQ will check for the Sprinkler heads each month when the monthly Preventative Maintenance Check List is completed to assure the spare sprinkler heads are available. If the heads are missing it will be reported on the Check List and the Administrator will obtain a new ones.	
	Exception No. 5: Not applicable Exception No. 6: Initiation of the fire alarm system is not required for existing installations in accordance with 33.2.3.5.5.			
1	SLOW Where an automatic sprinkler system is installed, for either total or partial building coverage, the system is in accordance with Section 9.7 and activates the fire alarm system in accordance with 33.2.3.4.1. The adequacy of the water supply is documented to the authority having jurisdiction.	:		

Printed: 01/25/2010 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION

A. BUILDING 0:

(X3) DATE SURVEY COMPLETED

13G010

B. WING

01/21/2010

NAME OF PROVIDER OR SUPPLIER

COMMUNICARE INC., #3 (POND)

STREET ADDRESS, CITY, STATE, ZIP CODE

	BOISE	, ID 83705		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K0056	Continued From page 2	K0056		
	Exception No. 1: Not Applicable			
	Exception No. 2: Not Applicable			
	Exception No: 3: In prompt and slow evacuation capability facilities where an automatic sprinkler system is in accordance with NFPA 13, Standard for the Installation of Sprinkler Systems, automatic sprinklers are not required in closets not exceeding 24 sq. ft. and in bathrooms not exceeding 55 sq. ft., provided that such spaces are finished with lath and plaster or material providing a 15 minute thermal barrier.			
	Exception No. 4: In prompt and slow evacuation capability facilities up to and including four stories in height, systems in accordance with NFPA 13R, Standard for the Installation of Sprinkler Systems in Residential Occupancies up to and Including Four Stories in Height, are permitted.	THE PROPERTY OF THE PROPERTY O		
	Exception No. 5: Not Applicable			
	Exception No. 6: Initiation of the fire alarm system is not required for existing installations in accordance with 33.2.3.5.5.	Tricky or an artist of the second of the sec		- 100
	IMPRACTICAL Where an automatic sprinkler system is installed, for either total or partial building coverage, the system is in accordance with Section 9.7 and activates the fire alarm system in accordance with 33.2.3.4.1. The adequacy of the water supply is documented to the authority having jurisdiction. 33.2.3.5.2.	 		
	Exception No. 1: Not Applicable.			ļ
	Exception No. 2: In slow and impractical]		i
			1-1-1-1-1-1	1

Printed: 01/25/2010 FORM APPROVED OMB NO. 0938-0391

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

COMMUNICARE INC., #3 (POND)

BOISE, ID 83705					
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEEDED B REGULATORY OR LSC IDENTIFYING INFORM	Y FULL	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K0056	Continued From page 3 evacuation capability facilities, an autom sprinkler system in accordance with NF Standard for the Installation of Sprinkler in One and Two Family Dwellings and Manufactured Homes, with a 30 minute supply, is permitted. All habitable areas closets are sprinklered. Automatic sprin not required in bathrooms not exceeding ft., provided that such spaces are finished lath and plaster or materials providing a minute thermal barrier. Exception No. 3: Not Applicable. Exception No. 4: Not Applicable. Exception No. 5: In impractical evacuatic capability facilities up to and including for in height, systems in accordance with N Standard for the Installation of Sprinkler in Residential Occupancies up to and In Four Stories in Height, are permitted. A habitable areas and closets are sprinkle Automatic sprinklers are not required in bathrooms not exceeding 55 sq. ft., provisuch spaces are finished with lath and praterials providing a 15 minute thermal Exception No. 6: Initiation of the fire alar is not required for existing installations in accordance with 33.2.3.5.5.	PA 13D, Systems water and klers are g 55 sq. ed with 15 on our stories FPA 13R, Systems cluding Il red. vided that blaster or barrier. m system	K0056		
	This Standard is not met as evidenced Based on observation, it was determined facility had not maintained the automatic sprinkler box supply as required. The co	d that the			!

Printed: 01/25/2010 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION

(X3) DATE SURVEY COMPLETED

13G010

A. BUILDING **02**B. WING _____

01/21/2010

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

COMMUNICARE INC., #3 (POND)

	BUISE	., 10 63705		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K0056	Continued From page 4 Observation on January 20, 2010 at 2:30 p.m.	K0056		
	disclosed that the sprinkler box had no fire sprinkler heads. No other sprinkler heads were available as required.			
	NFPA 101 9.7 AUTOMATIC SPRINKLERS AND OTHER			
	EXTINGUISHING EQUIPMENT 9.7.1 Automatic Sprinklers.			
	9.7.1.1* Each automatic sprinkler system required by another section of this Code shall be in	5		
	accordance with NFPA 13, Standard for the Installation of Sprinkler Systems.			
	Exception No. 1: NFPA 13R, Standard for the Installation of Sprinkler Systems in Residential			
	Occupancies up to and Including Four Stories in Height, shall be permitted for use as specifically referenced in Chapters 24 through 33 of this			
	Code. Exception No. 2: NFPA 13D, Standard for the Installation of Sprinkler Systems in One- and	**************************************		5
	Two-Family Dwellings and Manufactured Homes, shall be permitted for use as provided in Chapters			
	24, 26, 32, and 33 of this Code. NFPA 25 9.7.5 Maintenance and Testing.			
İ	All automatic sprinkler and standpipe systems required by this Code shall be inspected, tested,			
	and maintained in accordance with NFPA 25, Standard for the Inspection, Testing, and			:
ļ	Maintenance of Water-Based Fire Protection Systems.			1
	2-4.1.4 A supply of at least six spare sprinklers shall be			į
	stored in a cabinet on the premises for replacement purposes. The stock of spare	:		
!	sprinklers shall be proportionally representative of the types and temperature ratings of the system	!		
DRM CMS-	2567(02-99) Previous Versions Obsolete		W7\X2 If continuatio	n sheet Page 5 of

Printed: 01/25/2010 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION

A, BUILDING 02

(X3) DATE SURVEY COMPLETED

13G010

B, WING

01/21/2010

NAME OF PROVIDER OR SUPPLIER

COMMUNICARE INC., #3 (POND)

STREET ADDRESS, CITY, STATE, ZIP CODE

BOISE, ID 83705						
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE		
K0056	Continued From page 5 sprinklers. A minimum of two sprinklers of each type and temperature rating installed shall be provided. The cabinet shall be so located that it will not be exposed to moisture, dust, corrosion, or a temperature exceeding 100°F (38°C).	K0056				
The state of the s				7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7		
:						

PRINTED: 01/25/2010 FORM APPROVED

Bureau of Facility Standards STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X3) DATE SURVEY COMPLETED (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION IDENTIFICATION NUMBER: 02 A. BUILDING B. WING 13G010 01/21/2010

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

		2650 S. POND STREI 301SE, ID 83705			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FU REGULATORY OR LSC IDENTIFYING INFORMATI		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLET DATE	
M 000	16.03.11 Inital Comments	M 000		Opposition to have designed	
	The facility is a single story Type V (000) residential building. It is sprinklered in livi spaces and closets. It has a complete fire alarm/smoke detection system. Currently building is licensed for 8 ICF-MR beds. To survey was conducted in accordance with Life Safety Code, 2000 edition, Chapter 3 Existing Residential Board and Care Occulmpractical Evacuation Capability and IDA 16.03.11 Rules Governing Intermediate Compaction of the Mentally Retarded (ICF-Note The following deficiency was cited during fire/life safety survey on January 21, 2010. The annual fire/life safety survey was considered.	the the the 3, upancy, PA are MR).	RECEIVED FEB 1 6 2010 FACILITY STANDARDS		
 	Eric Mundell REHS Health Facility Surveyor Facility Fire/Life Safety and Construction Program				
MM309	16.03.11.110 Fire and Life Safety Standar	ds MM309	MM309		
:	Buildings on the premises used as facilities meet all the requirements of local, state an national codes concerning fire and life saf standards that are applicable to ICF/MR fa. This Rule is not met as evidenced by: Refer to CMS federal form 2567 and K tag.	nd ety acilities.	Please refer to KO56		
h 4h 40 0 7	•			2/0/10	
MM327	16.03.11.110.02(h) Emergency Electrical	Service MM327	MM327	2/9/10	
:	Each facility must provide emergency electorics for at least the exit passageway lighall lighting, and the fire alarm system.		The emergency light battery has been replaced and the light in question is		

021199

Alnievistrato

STATE FORM

W7VX21

2-11-2010 If continuation sheet 1 of 2

PRINTED: 01/25/2010 FORM APPROVED

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION

(X3) DATE SURVEY COMPLETED

13G010

02 A. BUILDING B. WING ___

01/21/2010

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

		POND STREET ID 83705			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIEN (EACH DEFICIENCY MUST BE PRECEDED REGULATORY OR LSC IDENTIFYING !NFO	BY FULL	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
MM327	Continued From Page 1 This Rule is not met as evidenced by Based on observation it was determined facility had not ensured that emerger was maintained for one of one units of census was six. The findings included Observation on January 20, 2010 at a disclosed that the facility had not main battery operated light used to illuminate alarm control panel. The light did nowhen the test button was activated. The light during a power failure would illuminate the panel controlling the firsystem.	ned that the cy lighting ested. The control of the	MM327	fully functional. Although the light did not function on January 21, 2010 it did function at the previous monthly test. We will continue to test the system monthly per our policy.	
TATE FORM	1	021199		W7VX21 If continu	uation sheet 2 of 2